	CLASSIFIED	MESSAGE	ROUTING	
25X1	Approved For Release 2003/11/25 : CIA	-RDP74B00836R	0004000104524	0 001
	UNIT ID/OSA TOPSE	CRET	2 074	1004
25X1	EXT	1. The distribution of the section o	3 I DEA	MOT
	DATE: 24 JULY 1964		A DAD	_ 14
25X1	TO :	and the space of the season property of the season of the	6 10 20	13
			7 85	nga at hada a manama manaman m 155
	FROM: DIRECTOR		8 R3	16
	DENDOICE		a	INITIALS
	CONF:		DEFERRED	PRIORITY
			ROUTINE	OPERATIONAL INITIALS
	INFO :		2	X IMMEDIATE
	05A1-15 DZ	_		17839 25X1
	MMEDIATE		CIJ4C	25/1
25X1	TO INFO		CITÉ	regions in the stands prioring stands in programme and the stands are stands as the stands are stands and the stands are stands and the stands are stands are stands and the stands are stands and the stands are
			<u> </u>	
25X1	IDEALIST TACKLE			:
• •				

25X1

25X1

- 1. WE HAVE BEEN UNABLE TO REACH CONCLUSIONS FROM ALL

 AVAILABLE EVIDENCE AS TO CAUSE OF LOSS OF U. 2 MISSION C184C

 OVER CHINA MAINLAND ON 7 JULY 1964. THERE IS TO DATE NO EVIDENCE

 OF AN INTERCEPTOR HAVING COME CLOSE ENOUGH TO THE MISSION

 AIRCRAFT TO SHOOT IT DOWN AND NO EVIDENCE OF SAM IN THE VICINITY

 OF LUNG-CHL
- 2. CAN YOU TASK YOUR SOURCES TO ATTEMPT TO DETERMINE IF FIGHTERS OR MISSILES WERE INVOLVED OR TO PRODUCE ANY OTHER INFORMATION THAT MIGHT SHED LIGHT ON THE CAUSE OF THE LOSS OF C184C. WILL KEEP YOU POSTED ON ANY NEW EVIDENCE RECEIVED HERE. WOULD APPRECIATE ANY THOUGHTS YOU MIGHT HAVE ON THE SUBJECT.

